

**Tank Storage Status**

Version Date:

4/16/2019 6:08

**Table 1: Response Tanks Storing Collected Response Liquids**

Tank #	Material Stored	Tank Max Capacity (bbls)	Current Level - Total (bbls)	Water Level (bbls)	Organic Total (bbls)	Comment/Activity
80-18	Firefighting Water/Organics	71,508	69,075	25,121	43,954	No Activity
80-33	Firefighting Water/Organics	72,528	50,554	18,498	32,056	Active via Vacuum Trucks
100-28	Firefighting Water/Organics	100,297	84,187	46,093	38,094	Active via Vacuum Trucks
100-31	Firefighting Water/Organics	100,255	99,923	90,666	9,257	No Activity
100-15	Firefighting Water/Organics	100,256	24,348	9,105	15,243	Transferring to 100-1
100-1	Firefighting Water/Organics	100,074	80,698	80,543	155	Transferring 100-15 to 100-1
		544,918	408,785	270,026	138,759	
	Available Storage	136,133				

**Table 2: ITC Wastewater System Tanks**

Tank #	Material Stored	Tank Max Capacity (bbls)	Current Level - Total (bbls)	Water Level (bbls)	Organic Total (bbls)	Comment/Activity
50-2	Prior Wastewater/Firefighting Water/Organics	52,084	50,878	50,689	189	
80-34	Prior Wastewater/Firefighting Water/Organics	80,287	61,808	56,629	5,179	
60-1	Prior Wastewater/Firefighting Water/Organics	54,384	50,631	44,272	6,359	
		186,755	163,317	151,590	11,727	

**Table 3: Temporary Storage Vessels Loaded**

Barge	Prior Wastewater/Firefighting Water/Organics	57,000	49,157	49,157		
-------	--	--------	--------	--------	--	--

**Table 2: Impacted Tank Farm Information**

Tank #	Material Stored Prior to Event	Safe Operating Capacity (bbls)	Current Level - Total (bbls)	Quantity Prior To Event (bbls)	Comment/Activity	Physical Status Of The Tank
80-1	Base Oil	72,978	0	49,760	COMPLETE - No Further Action Required	Tank erect, charred, damage to roof
80-2	Gas Blendstock	74,189	0	42,260	COMPLETE - No Further Action Required	Collapsed
80-3	Gas Blendstock	69,679	0	33,410	COMPLETE - No Further Action Required	Tank erect, charred, but heavily damaged
80-4	Base Oil	74,497	0	35,699	COMPLETE - No Further Action Required	Tank erect, charred, damage to roof
80-5	Xylene	72,859	Sludge	38,426	Cleaning In Progress; Additional cleaning equipment mobilized	Collapsed
80-6	Gas Blendstock	74,789	0	49,414	COMPLETE - No Further Action Required	Collapsed
80-7	Pygas	75,373	900	43,595	Degassing	Half of the tank standing, roof collapsed
80-8	Naphtha	73,960	400	70,761	West Manway Open - Organic Removal In Progress	Collapsed
80-9	EMPTY	76,521	0	Empty	COMPLETE - No Further Action Required	Collapsed
80-10	Pygas	74,767	200	14,382	Cleaning In Progress; Degassing	Erect, fixed roof in tact
80-11	Base Oil	76,208	3,000	52,902	Organic Removal In Progress	Erect, charred, and damage to roof
80-12	EMPTY	76,502	0	Empty	COMPLETE - No Further Action Required	Partially Collapsed
80-13	Toluene	70,523	0	14,725	COMPLETE - No Further Action Required	Erect, fixed roof in tact
80-14	Pygas	72,965	Sludge	15,840	Cleaning In Progress; Degassing	Collapsed
80-15	Pygas	74,692	Sludge	9,421	Cleaning In Progress - Additional Solids Removal In Progress	Collapsed
		1,110,502	4,500	470,595		

	Full of Product / No action	EMPTY	No organics in the tank
	Heel / Residual Remaining - In Process	Clean	Tank has no organics and has been rinsed and cleaned
	Cleaning or Degas	Ready to Clean	Product removed, man ways open, and ready for tank cleaning to begin
	COMPLETE - No Further Action Required		